

Collision with Jerol Ramp Metering Signal Post on the M1

A Light Goods Vehicle collided with a Jerol 219mm twin head signal post on the M1 in August 2008.

The post behaved as we would expect for this type of impact, falling close to the impact point. The van incurred minimal damage and we are informed that the driver walked away uninjured. Once again, no secondary collision occurred.

See photo below...

